403-13692 STOP SIGN EVALUATION Traffic Request Number: Traffic Study Number: IN HOUSE Traffic Study Date: 4/25/18 Time: 11:30-11:45 GABACHO DRIVE/MONTEGO DRIVE Main Street: **REMORA STREET** Side Street: Existing condition: UNCONTROLLED INTERSECTION Requires 15 or more points for Stop Sign Qualifies for Stop Sign based on other criteria? (Y/N) ACCIDENT EXPERIENCE Recent 3 year period: 4/27/15 to 4/27/18 0 Point(s) # Acc = 0 VISIBILITY CONDITIONS 17 17 A = Main Street: Gabacho Drive/Montego Drive B = 40 40 Width (FT) =35 Y D C = 17 17 Parking (Y/N) ? D= 25.5 25.5 a" (FT) = 5 (Distance from curb to view obstr.) DI= 17.714 18 d''(FT) =5 (Distance from curb to view obstr.) Dr= 21.161 21 D= 17.714 Side Street: Remora Street 3.3257 64 Y Width (FT) =В V= 6.4323 Parking (Y/N)? С V= 6.4323 V= 6.4 b" (FT) = 5 (Distance from curb to view obstr.) c" (FT) = 5 (Distance from curb to view obstr.) Critical Approach Speed : MPH 9 Point(s) TRAFFIC & PEDESTRIAN VOLUMES Gabacho Drive/Montego Drive Main Street: Sum of the main street approaches
Vol = 14 (15 Minute Count) (Peak Hour Count) (ADT Count) 932 (24 hour volume) 5 Point(s) Remora Street Side Street: Sum of the side street approaches 15 (15 Minute Count) (Peak Hour Count) Peds crossing side Street: 0 (15 Minute Count) (Peak Hour Count) 100 (Peak Hour Volume) 3 Point(s) SPECIAL CONDITIONS Enter 0 - 3 points: 1 Describe: TIERRASANTA ELEMENTARY SCHOOL 1 Point(s) TOTAL 18 POINT(S) Qualifies for Stop Sign based on visibility

Investigator RD Date: 4/27/18 4 27 118