403-140638 STOP SIGN EVALUATION Traffic Request Number: IN-HOUSE Traffic Study Number: Traffic Study Date: 7/9/19 Time: 10:14-10:29 **CAMINO PLAYA MALAGA** Main Street: Side Street: **CAMINO PLAYA ACAPULCO** Existing condition: UNCONTROLLED INTERSECTION Requires 15 or more points for Stop Sign Qualifies for Stop Sign based on other criteria? (Y/N) ACCIDENT EXPERIENCE Recent 3 year period: 7/12/16 to 7/12/19 0 Point(s) # Acc = 0 VISIBILITY CONDITIONS 20 A = 20 Main Street: Camino Playa Malaga B= 24 24 Width (FT) =36 Y D C = 22 22 Parking (Y/N) ? D= 29 29 a" (FT) = 8 (Distance from curb to view obstr.) DI= 16.581 17 d" (FT) = 8 (Distance from curb to view obstr.) Dr= 27.25 27 D= 16.581 Side Street: Camino Playa Acapulco 3.2655 v= 26 Y Width (FT) =V= 6.0886 Parking (Y/N)? С V= 6.0886 V= b" (FT) = 10 (Distance from curb to view obstr.) c" (FT) = 10 (Distance from curb to view obstr.) Critical Approach Speed : 6 MPH 9 Point(s) TRAFFIC & PEDESTRIAN VOLUMES Camino Playa Malaga Main Street: Sum of the main street approaches Vol = 9 (15 Minute Count) (Peak Hour Count) (ADT Count) 1 Point(s) 599 (24 hour volume) Camino Playa Acapulco Side Street: Sum of the side street approaches Vol = 1 (15 Minute Count) (Peak Hour Count) Peds crossing side Street: Vol = 1 (15 Minute Count) (Peak Hour Count) 13 (Peak Hour Volume) 0 Point(s) SPECIAL CONDITIONS Enter 0 - 3 points: Describe: 0 Point(s) TOTAL 10 POINT(S) Qualifies for Stop Sign based on visibility

Investigator: **RD** Date: 7/12/19

12 119